

Inspection Report

Report ID: HV-20260710-1783647390829
Date: July 10, 2026

Customer Details

Company: REDLINE LOGISTICS
Contact: CHRIS HALL
Phone: 0427 690 330
Email: chris.hall@redlinelogistics.com.au

Vehicle Details

Registration: SKA278
Description: 2023 VOLVO FH16
VIN: TDJ4HE861G6RCW7BD
Odometer: 146556 km

Summary

91
OK

0
Advisory

1
Defect

9
N/A

Service Performed

Service Type: B Service

Service Item	Action
Engine oil	Replaced
Oil filter	Replaced
Fuel water separator	Replaced
Fuel filter	Replaced
Air filter	Cleaned
Tyre pressures	Topped Up
Grease points	Lubricated
AdBlue/DEF	Topped Up

Defect Items

Tyres & Wheels

Tyre Tread Depth & Condition

Notes: LH steer worn

DEFECT



OK Items

Identification & Details

Registration Plates Affixed and Legible	OK	Compliance plate affixed	OK	VIN / fleet number visible	OK
Odometer recorded	OK	Vehicle registration expiry checked	OK		

Cabin, Seats & Controls

Seats - mountings / condition	OK	Seat belts - operation / condition	OK	Dashboard warning lights	OK
Gauges & instruments	OK	Horn	OK	Steering wheel	OK
Pedals	OK	Windscreen Wipers & Washers	OK		

Glazing & Visibility

Windscreen / Glass	OK	Window operation	OK	Rear vision mirrors	OK
--------------------	----	------------------	----	---------------------	----

Lights & Electrical

Park / Tail / Number Plate / Clearance Lights	OK	Headlights / auxiliary lights	OK	Brake lights	OK
Indicators / warning devices	OK	Reflectors / lenses	OK	Warning beacons	OK
Battery & isolator	OK				

Exterior, Body & Fittings

Body corrosion / security / damage	OK	Panels & guards	OK	Doors / Bonnet / Catches	OK
Body fittings / bumper bars	OK	Steps & grab handles	OK	Rear marker plates	OK
Mudguards / mud flaps	OK	Load securing points	OK		

Tyres & Wheels

Wheels / rims / wheel nut security	OK	Wheel bearings	OK	Spare Wheel (if fitted)	OK
------------------------------------	----	----------------	----	-------------------------	----

Engine Bay

Engine oil	OK	Coolant	OK	Belts & hoses	OK
Fuel system	OK	Air intake	OK	Engine / fuel leaks	OK

Braking System

Brake components	OK	Service brake operation	OK	Parking brake operation	OK
Air lines & fittings	OK	Air tanks	OK	Brake chambers	OK
ABS warning	OK				

Air Systems

Air system leaks / low air warning / contamination	OK	Breakaway protection	OK
--	----	----------------------	----

Steering

Steering box / pitman arm	OK	Arms / linkages / wheel	OK	King pins	OK
Steering free play	OK	Steering leaks	OK		

Suspension & Axles

Springs	OK	Hangers / pins / bushes	OK	Air bags / air suspension	OK
Shock absorbers	OK	Axles / cross members	OK	U-bolts	OK
Ride height	OK				

Driveline

Gearbox	OK	Tailshaft	OK	Differential	OK
Grease nipples	OK	Engine / transmission mountings	OK	Mounts & joints	OK
Driveline leaks	OK				

Exhaust & Emissions

Exhaust system condition / leaks / security	OK	DPF (if fitted)	OK	Emissions	OK
---	----	-----------------	----	-----------	----

Underbody & Chassis

Chassis rails - cracks / security	OK	Cross members	OK	Structural damage	OK
Corrosion	OK	Fuel tanks & mounts	OK	Body mountings	OK

Tow Couplings

King pin / skid plate	OK	Ball race turntable	OK
-----------------------	----	---------------------	----

Road Test

Engine performance under load	OK	Turbo / boost response (if fitted)	OK	Transmission operation / shift quality	OK
Clutch operation (if manual)	OK	Retarder / engine brake operation (if fitted)	OK	Service brake performance	OK
Park brake holding	OK	Steering response / wander	OK	Suspension / ride quality	OK
Noise / vibration	OK	ABS / warning lights during drive	OK	Air system recovery time	OK

N/A Items

Tow Couplings

Auto tow couplings	N/A	Tow eye / drawbar / safety chains	N/A	Gooseneck	N/A
--------------------	-----	-----------------------------------	-----	-----------	-----

High Voltage Systems

High voltage system damage / shorting / security	N/A	High voltage warning lights	N/A	High Voltage Labelling	N/A
--	-----	-----------------------------	-----	------------------------	-----


Gas Systems (LPG, NG, H2)

Gas system damage / leaks / security	N/A	Gas system warning lights	N/A	Gas System Labelling	N/A
--------------------------------------	-----	---------------------------	-----	----------------------	-----

Signatures

Inspector Signature

Name: JJ

A handwritten signature in black ink, consisting of a large loop followed by a series of smaller, connected loops and a horizontal line at the end.

Signature

Date: July 10, 2026

Disclaimer

This report documents the condition of the vehicle or equipment at the time and date of inspection only. The inspection was visual and non-invasive; no dismantling, testing under load, or verification of internal components was performed unless explicitly stated. No representation, warranty, or guarantee (express or implied) is made regarding the future condition, safety, roadworthiness, compliance, or fitness for purpose of the vehicle or equipment.

To the fullest extent permitted by law, the inspector and issuing company accept no responsibility or liability for any loss, damage, defect, failure, or consequence arising from reliance on this report, including defects that were hidden, latent, intermittent, or not reasonably detectable at the time of inspection.